

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|-----|
| Date: | 06/10/2009 | Originator: | DS |
| TIB #: | PSB.2009.06.002 | Authorization: | Kps |
| Reference: | TI 09-08j Rev. A | Total Pages: | 8 |
| Product(s): | PowerLite 735c / 737c / 745c / 755c / 765c / 835p / 1705/1715/1815/1825/7850p / 8300 with EasyMP.net option, Pro G5150/G5350 / 1725 / 1735W / 85 / 825 / 826W | | |
| Subject: | Release of EMP NS Connection for Windows & Mac Upgrade from v2.50 to v2.51 | | |

This bulletin was created to inform you of the release of the new version 2.51 of the EMP NS Connection software.

Description of Change:



Improvements have been made to the EMP NS Connection utility.

Reason:


The improvements to NS Connection V2.51 are as follows

Improvements (V2.50 (V2.51


| | |
|--------------|--|
| Improvements | <ul style="list-style-type: none">■ Addition of 10 new languages: Arabic, Ukrainian, Romanian, Indonesian, Croat, Slovak, Bulgarian, Malay, Vietnamese and Hebrew.■ Addition of troubleshooting function (Windows Only) When pressing the troubleshooting button, the corresponding troubleshooting and error number is displayed in the error message window.<ul style="list-style-type: none">• When experiencing problems with NS Connect, please report to Epson the error number along with the failure information. |
|--------------|--|



Error number



Also you can access troubleshooting by clicking **Start → All programs → EPSON Projector → EMP NS Connection → EMP NS Connection V2.51 Troubleshooting.**



- Fixed error message displayed by the NVIDIA utility

Failure Symptom

When starting Quick Wireless/USB Display/NS Connection on a PC with the built-in NVIDIA graphics chip (ex. ThinkPadT61 NVIDIA Quadro NVS 140M/NVIDIA Quadro FX 570M Display Driver), the NVIDIA utility displays consecutive error messages. As a result, some PCs will experience a lock-up.

Countermeasure

Hardware acceleration level is set to 3 when Quick Wireless/USB Display/NS Connection are being used.

Limitation

By setting hardware acceleration level to “3”, the mouse cursor flickers more visibly than the setting of “None”. This symptom can be avoided by unchecking the box for **Transfer Layered Window** on the Adjustment performance tab in the **Set Options** window of NS Connection.

Note: When NS connection is being used, and the hardware acceleration setting is changed manually, at next startup, NS connection starts with the same setting level of hardware acceleration.

| | |
|------------|--|
| Limitation | <p><u>All Operating Systems</u></p> <ul style="list-style-type: none"> • When using EAP type of security that consumes a lot of CPU resources, projectors may disconnect from NS connection. The solution is to click Set Options of NS Connection and set Adjust Performance to Fast. • It takes more time for the PowerLite 1725 / 1735W / 1825 / Pro G5150 / Pro G5350 projectors to disconnect from NS connection as compared to the PowerLite 1705 / 1715 / 1815 projectors, due to the limitation of the new OS (WindowsCE) on IM-X4 projectors. • To avoid conflicts between the Quick Wireless and other makers' utilities, when the Quick Wireless starts, this version stops services of the other utilities listed in the attached file (Exhibit 1). When quitting Quick Wireless, the other utilities resume their services. • In the network environment using IEEE 802.11 b/g standards, the wireless connection may drop under the following conditions. Due to specification of wireless controllers, some wireless controllers don't send their beacon periodically. Even if a projector is connected to a PC via wireless, if the projector doesn't detect the beacon for 11b signal for a certain period (30 – 60 seconds) from the PC, the projector judges that there isn't any PC using the 11b signal in the network and switches to communication with 11g (default) signal. On the other hand the PC still tries to communicate with 11b. As a result, the wireless connection between the projector and the PC drops. <p><u>Solutions to this problem:</u></p> <ol style="list-style-type: none"> a. Establish a wireless communication between the PC and projector via 802.11a signal. <p><u>Windows OS</u></p> <ul style="list-style-type: none"> • Due to a limitation of the module VLC for the Movie Sending mode of the IM-X4 version projectors, when IM-X4 projectors display MPEG2 and WMV images in Movie Sending mode via NSC V2.40, fast-forward and rewind functions cannot be used. When IM-X3 projectors display MPEG2 via NSC V2.40, fast-forward and rewind functions can be used. <p><u>Windows Vista OS</u></p> <ul style="list-style-type: none"> • Multi screen display function cannot be used • Virtual display driver cannot be installed in PC. • When UAC (User Account Controls) screen is being displayed, the projected image pauses. • The Motion picture of Windows photo gallery cannot be projected in full-screen mode. • Still images and motion pictures from Windows Media Center cannot be projected in full-screen mode. • Since NS Connection can capture Layered windows, the tool bar of NS Connection is projected. • • • When projecting images via NS Connection, mouse cursor might blink depending on PC specification. |
|------------|--|

| | |
|--|---|
| | <p>Macintosh OS</p> <p>In case of uninstalling NSC V2.20 or later version, it is possible to uninstall by following 2 methods.</p> <ul style="list-style-type: none"> - Delete by installer exclusively for NSC version which you want to uninstall. <p>For example, when you want to uninstall NSC V2.40, you need to use installer for NSC V2.40. NSC V2.20 and later version can not be uninstalled automatically by different version installer.</p> <ul style="list-style-type: none"> - Delete manually. |
|--|---|

System Requirements:

| | |
|----------------------------------|---|
| OS | Windows 2000 SP4/ XP Home Edition/ XP Professional(32bit) /Vista SP1 Home Basic / Home / Premium / Ultimate / Business / Enterprise(32bit) Mac OS X 10.3 minimum, OS 10.3.9/10.4.5/10.5.1 recommended |
| CPU | Windows: Mobile Pentium III 1.2GHz at least (Pentium M1.6GHz at least recommended) Mac: Power PC G3 900MHz at least recommended |
| Memory | At least 256MB (At least 512MB recommended) |
| Available hard disk space | At least 20MB |
| Display | Minimum- VGA(640×480), Maximum- UXGA (1600 x 1200) 16-bit color or more |

Obtaining the Update:

Download epon13123.exe from www.epson.com to the version 2.50 update for NS Connection.

The files are extracted and copied to C:\EPSON\epson13123_EMP_NS_Connection_251. The user should be directed to this folder to find the bulletin. The program will automatically install after the download file is extracted.

Note: on the Mac, the extraction process copies the epon13124_EMP_NS_Connection_251 folder to the desktop. The program and bulletin are inside this folder. The user will double-click on NSCv2.51_Installer to start the installation process.

Software Upgrade History:

| Version | Release date | Remarks |
|---------|-------------------|---|
| 1.00 | December 25, 2002 | New release |
| 1.10 | January 1, 2003 | Release for PowerLite 7850p |
| 1.20 | September 10, | Improved the transfer rate specification for PowerPoint |

| | | |
|------|------------------|---|
| | 2003 | images |
| 1.30 | May 31, 2004 | Support added for WPA and LEAP |
| 1.31 | June 18, 2004 | Improved screen problem issue |
| 1.32 | January 18, 2004 | Improved the internal function of connecting to the projector |
| 1.40 | April 1, 2005 | <ul style="list-style-type: none"> • Addition of Presentation Mode and Interruption Prevention function • Able to present with video set for 32 bit color • Function improvement with Excel and PowerPoint • Improved ESSID search lockup prevention when certain LAN adapters and drivers are used |
| 2.00 | 2006/06/20 | <ul style="list-style-type: none"> • Addition of multi screen display function • Addition of movie sending mode • - Improvement of connection and usability |
| 2.10 | 2006/12/08 | <ul style="list-style-type: none"> • Improvement in the ability to search projectors by Automatic Search. (For Windows) • Improvement in the operability of choosing projector. • Improvement in operability and visibility of "Connect" button. • Preventing Virtual Display from being used as primary display. • Improvement in the ability of image processing speed. (For Mac) • - Change the packet size for a connection request command used by Quick connection. |
| 2.20 | 2006/05/29 | EMP NS Connection V2.20 supports Windows Vista (Home Basic /Home Premium/Ultimate/Business/Enterprise). |
| 2.30 | Nov. 27, 2007 | <ul style="list-style-type: none"> • Supported picture transfer for EMP-1825 • Improved wireless search and connection abilities. • - Added video format supporting movie sending mode |
| 2.40 | Mar. 24, 2008 | <ul style="list-style-type: none"> • EMP NS Connection V2.40 supports Windows Vista Service Pack 1 • - Supports 24 languages |
| 2.50 | Jun.2,2008 | Supported image transfer and virtual display of 1280 x 768 <ul style="list-style-type: none"> • Changed the operation method to prevent NS connection from being blocked by Windows Firewall Added another wireless LAN utility that NS connection supports |
| 2.51 | Feb.9,2009 | <ul style="list-style-type: none"> - Addition of supported models (PowerLite-85/825/826W) - Addition of supported languages - Addition of troubleshooting function (Only for Windows) |

[Exhibit 1] Wireless LAN client list that NSC V2.30 and V2.40 stops their service process

| | Manufacturer Name | Adapter Name | Wireless LAN Utility Name |
|--------------------|-------------------|---|--|
| Supported by V2.30 | D-Link | Air Plus XTREMEG DWL-G650 | D-Link AirPlus XtremeG Utility (CD) |
| | NETGEAR | WN511T | Smart Wireless Utility Ver.1.1.5.9(CD) |
| | BUFFALO | Buffalo all products | Client Manager 3 Ver.1.2.10(Web) |
| | IBM | ThinkPad products | Access Connection(Web) *1 Ver.4 or later |
| | IBM | ThinkPad products | Access Connection(Web) *1 Ver.3.71 |
| | Logitec | Logitec LAN-WAG/U2 Wireless LAN Adapter | Logitec Wireless LAN Client Utility |
| | Linksys | Wireless-G Notebook Adapter v.5.0 | WPC54G-JP setting utility |
| | NETGEAR | WG511AJP | NETGEAR WG511A Smart Wizard Ver3.2.3.306 |
| | NETGEAR | WGM511 | NETGEAR SMART WIZARD -Wireless Assistant WGM511 Ver 1.0.0.7 |
| | NETGEAR | WPNT511 | NETGEAR WPNT511 SMART WIZARD Ver1.1.3.0 |
| | Linksys | WPC300N | Wireless-N Notebook Adapter Wireless Network Monitor v1.05 |
| | Linksys | WPC54G | Wireless-G Notebook Adapter Wireless Network Monitor Ver 3.1 |
| | Linksys | WPC54GX4 | Wireless-G Notebook Adapter with SRX400 Setup Wizard V1.1 |
| | Linksys | WUSB54GP | Wireless-G Portable USB Adapter WLAN Monitor v1.05 |
| | Linksys | WUSBF54G | Wireless-G USB Adapter with Wi-Fi Finder |
| | NETGEAR | WG511 v2 | |

| | | | |
|---|----------|-------------------|--|
| | Linksys | WPC54GX | Wireless-G Notebook Adapter With SRX Wireless Network Monitor v. 1.2 |
| Supported by V2.40 | Linksys | WUSB54GSC | Compact Wireless-G USB Adapter Wireless Network Monitor v1.05 |
| Supported by Quick Wireless Connection V.1.00 / NSC V2.50 | Atheros | | Atheros Client Utility |
| Supported by Quick Wireless Connection v1.02 / NSCv2.51 | Broadcom | BCM4311 / BCM2050 | Broadcom Wireless Utility |
| | NETGEAR | WN511B | NETGEAR WN511B Smart Wizard Utility |
| | NETGEAR | WG111v3 | NETGEAR WG111v3 Smart Wizard Utility |
| | NETGEAR | wn111 | NETGEAR WN111 Smart Wizard Utility |
| | NETGEAR | WUSB600N | Linksys Wireless Network Monitor |
| | PLANEX | GW-US300MiniW | PCI GW-US300MiniW Utility |

*1: Because Access Connection service stops, power display of Power Manager becomes invalid.

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|------------|
| Date: | 04/20/2009 | Originator: | JAM |
| PSB #: | PSB.2009.06.001 | Authorization: | <i>Kas</i> |
| Reference: | TI 09-05e Rev. A/B | Total Pages: | 5 |
| Product(s): | PowerLite 735c / Cinema 500 / 737c / 745c / 755c / 765c / 830p / 835p / 1705c / 1715c / 6100i / 6110i / 7800p / 7850p / 7900NL / 8300i / 8300i with EasyMP.net module / 9300NL / 1815p / 1825 / 822p / 83c / 822+ / 83+ / G5000 / Pro G5150 / Pro G5350 / Pro G5200W / 1725 / 1735W / 400W / 410W / 84 / 85 / 825 / 826W PowerLite 61p / 81p / 82c / 821p / 1810 / 260d (Latin America) / 280d (Latin America) with TCP/IP to Serial converter | | |
| Subject: | Release of EMP Monitor for Windows version 4.30 | | |

This bulletin was created to inform you of the release of the new version 4.30 of the Epson EMP Monitor software utility.

Description of Change:

Improvements have been made to the EMP Monitor software utility.

Note: For the PowerLite 61p / 81p / 82c / 821p / 1810 / 260d (Latin America) / 280d (Latin America) models, a serial to TCP/IP conversion adapter is necessary. The function of Auto Update does not work for these models. You need to manually click on refresh to get an updated status of projectors.

Reason:

The improved points of version 4.30 are as follows:

| | |
|-------------------------|--|
| Application | EMP Monitor |
| Version upgraded | Version 4.22 → Version 4.30 |
| Improved points | (1) Addition of 7 new languages - Indonesian, Croat, Slovak, Bulgarian, Malay, Vietnamese, and Hebrew Existing 27 languages - Chinese (Traditional), Netherlands, Danish, Polish, Hungarian, Czech, Romanian, Slovene, Norwegian, Swedish, Finnish, Russian, Ukrainian, Greek, Turkish, Arabic (Windows NT4 does not support), English, Japanese, French, German, Italy, Spanish, Portuguese, Chinese (Simplified), Korean, Catalan, Thai |

(2) Addition of Input Source (Only PowerLite 84 / 85 / 825 / 826W)
Previous version of EMP Monitor included USB Display, USB and LAN as one source: EasyMP.

The input source buttons for USB display, USB, and LAN are available as separate input sources as shown below:

- Old version - EMP Monitor V4.22

EMP Monitor V4.22



- New version - EMP Monitor V4.30


EMP Monitor V4.30



(3) New feature for the PowerLite 84 / 85 / 825 / 826W.

Displays projector's serial number in the Menu settings

- The projector's serial number is now displayed in the projector's menu under "info",
- EMP Monitor can also display the projector's serial number as shown below:



| | |
|--------------------|---|
| Limitations | When the PowerLite1725 / 1735W exhibit a Lamp Cover Open error state, EMP Monitor cannot detect the error. The reason is that when the lamp cover is opened, the primary power source that reports the error state to EMP Monitor is turned off immediately. This is different from other models which make the secondary power source turn off under the same condition. |
|--------------------|---|

Note: EMP Monitor Ver. 4.xx is not compatible with EMP Monitor Ver. 3.05 and earlier versions. EMP Monitor Ver. 4.xx cannot read the setting files of EMP Monitor Ver. 3.05 and earlier versions.

System Requirements:

| | |
|---------------|--|
| OS | <ul style="list-style-type: none"> Windows 98 SE / Me / NT 4.0 (SP6) *Except Arabic and Hebrew / Windows 2000 Pro / XP Home Edition / XP Professional (32 bit) / Vista Home Basic / Home Premium / Ultimate / Business / Enterprise (32 bit) *Except Ukrainian / Vista SP1 Home Basic / Home Premium / Ultimate / Business / Enterprise (32 bit) Internet Explorer Ver. 5.0 or later must be installed |
| CPU | Minimum: Pentium MMX 166 MHz (Recommended: Pentium II 233 MHz or higher) |
| Memory | At least 64 MB (Recommended: 128 MB or above) |

| | |
|----------------------------------|---|
| Available hard disk space | At least 50 MB |
| Display | SVGA (800×600) or higher resolution, 32 bit or higher display color |

Obtaining the Update:

Download epson13055.exe from www.epson.com to get the version 4.30 update for EMP Monitor. The files are extracted and copied to C:\EPSON\epson13055_emp_monitor_430.

This file is a self-extracting archive and will start the installation utility for EMP Monitor. Follow the on-screen instructions during the installation process.

Software Upgrade History:

| Version | Release date | Remarks |
|-------------|----------------------|--|
| 3.00 | December 25, 2002 | Supported PowerLite 735c |
| 3.01 | February 26, 2003 | Supported PowerLite 7800p / 8300i |
| 3.02 | April 18, 2003 | Supported PowerLite 7850p / 8300i with EasyMP.net option module |
| 3.03 | November 21, 2003 | Supported PowerLite Cinema 500 |
| 3.04 | April 1, 2004 | Supported Serial -TCP/IP conversion adapter for PowerLite 61p / 81p |
| 4.01 | October 18, 2004 | Supported projectors that are configured on a large-scale network. |
| 4.02 | August 29, 2005 | Addition of timer function and auto search function by specifying IP addresses. Improvement of communication logs size. |
| 4.10 | May 8, 2006 | Addition of new functions, Improvement of usability, and Corresponding to PowerLite 6100i. |
| 4.20 | May 15, 2007 | EMP NS Connection V2.20 supports Windows Vista (Home Basic / Home Premium / Ultimate / Business / Enterprise). |
| 4.21 | September 26, 2007 | Supported 25 languages |
| 4.22 | March 31, 2008 | Supported 27 languages Addition of new Error Information Supported Video (BNC) |
| 4.30 | April 3, 2009 | Supported 34 languages Additional Input Sources Displays projector's serial number in Menu settings |

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|-----|
| Date: | 12/18/2008 | Originator: | DS |
| PSB #: | PSB.2009.01.006 | Authorization: | Kps |
| Reference: | TI 08-22e Rev. A/B | Total Pages: | 7 |
| Product(s): | PowerLite 735c / 737c / 745c / 755c / 765c / 835p 1705c / 1715c / 1815p / 1825p / 7850p / 8300i with EasyMP.net option Pro G5150 / Pro G5350 / 1725 / 1735W | | |
| Subject: | Release of Check Tool for Network Projectors V1.00 (for Windows) | | |

This bulletin was created to inform you about the release of Epson Check Tool software for Network Projectors version 1.00.

Description of Change:

First release of the Check Tool for Network Projectors for Windows

Reason:

The Check Tool for Network Projectors makes it possible to easily check whether EPSON Quick Wireless Connection and EMP NS Connection's Quick Connection mode can operate on the users' Windows PC properly. The Check Tool for Network Projector can also be used as a reference check before the purchase of the projector or as a troubleshooting Tool.

1) Function of the Application


| Application name | Check Tool for Network Projector V1.00 |
|------------------|---|
| Notes | <p>The Check Tool checks automatically whether EMP Quick Wireless Connection and EMP NS Connection's Quick Connection mode can operate properly on the user's Windows PC in terms of the following four points:</p> <ol style="list-style-type: none">1. Checks OS support.<ul style="list-style-type: none">• Checks whether the OS is supported by EMP Quick Wireless Connection / EMP NS Connection.2. Checks user account<ul style="list-style-type: none">• Checks user's account for administrator privileges to install EMP Quick Wireless Connection / EMP NS Connection.3. Checks the wireless LAN adapter<ul style="list-style-type: none">• Checks whether the wireless LAN adapter and driver are installed on the PC.• Checks whether the wireless LAN is active. |

Notes

4. Checks wireless LAN switching

- Checks whether wireless LAN adapter is turned ON.
- Checks whether EMP Quick Wireless Connection and EMP NS Connection's Quick Connection mode can set the SSID on the user's PC when trying to connect to a projector using EMP Quick Wireless Connection and EMP NS Connection's Quick Connection Mode.

The Check Tool checks for communication conflict and whether it can actually stop the utilities when both utilities--EMP Quick Wireless Connection V1.00 and EMP NS Connection-- are both installed on the users PC.



| | |
|--------------------|---|
| Notes | <p>Output of the log file:</p> <ul style="list-style-type: none"> The Check Tool records the result in a text file (log file). Usually, the log file is saved under the name of CheckInfoDATE.log in the directory where "EB_CHT.exe" is stored |
| Limitations | <ul style="list-style-type: none"> When the Check Tool is checking the user's PC, the user's PC drops off network. The Check Tool does not check whether the firewall of manufacturers of security software other than Windows may be blocking EPSON Quick Wireless Connection/EMP NS Connection. |

2) Operating Environment

Check Tool for Network Projector V1.00


| | |
|------------|---|
| OS | Windows 2000 SP4 Rollup1 / XP Home Edition/ XP Professional(32bit) non-SP,SP1,SP2,SP3 /Vista SP1 Home Basic/Home Premium/Ultimate/Business/Enterprise(32bit) non-SP,SP1 |
| CPU | Windows: Mobile Pentium III 1.2GHz at least (Pentium M1.6GHz at least recommended) |
| Memory | 256MB at least (Recommendation: 512MB at least) |
| Disk space | 20MB at least |
| Display | Resolution: At least VGA(640 x 480) but no more than UXGA (1600 x 1200) At least 16 bit color |

- 3) **Location of download file: Check Tool for Network Projector V1.00**
Download `epson12794.exe` from the Epson website (www.epson.com).
This is a self-extracting file; please follow the screen prompts to install the Check Tool software.
- 4) Double-click the `[EB_CHT.exe]` icon
- 5) Read the contents of the `[SOFTWARE LICENSE AGREEMENT]`, and click the `[Agree]` button.
- 6) A dialog indicating the program is starting opens with the following message:

This tool cuts off the network connection temporarily.
Click the `[Start]` button to begin verification.




- 7) The Check tool dialog is displayed. It takes a few minutes for the results of the verification are displayed



- 8) When two or more wireless LAN adapters are available on your computer, the adapter selection dialog opens.

Select the wireless LAN adapter and press the OK button to continue.



9) When the verification is complete, the result is displayed on the bottom of the dialog.

The result is stored in the same folder as the check tool.

File Name: CheckInfo<****>.log

**** indicates the created date and time.

[Exhibit 1]

Wireless LAN client list that NSC and Quick Wireless Connection stop their service process

| | Manufacturer Name | Adapter Name | Wireless LAN Utility Name |
|------------------------|-------------------|---|--|
| Supported by NSC V2.30 | D-Link | Air Plus XTREMEG DWL-G650 | D-Link AirPlus XtremeG Utility (CD) |
| | NETGEAR | WN511T | Smart Wireless Utility Ver.1.1.5.9(CD) |
| | BUFFALO | Buffalo all products | Client Manager 3 Ver.1.2.10(Web) |
| | IBM | ThinkPad products | Access Connection(Web) *1 Ver.4 or later |
| | IBM | ThinkPad products | Access Connection(Web) *1 Ver.3.71 |
| | Logitec | Logitec LAN-WAG/U2 Wireless LAN Adapter | Logitec Wireless LAN Client Utility |
| | Linksys | Wireless-G Notebook Adapter v.5.0 | WPC54G-JP setting utility |
| | NETGEAR | WG511AJP | NETGEAR WG511A Smart Wizard Ver3.2.3.306 |
| | NETGEAR | WGM511 | NETGEAR SMART WIZARD - Wireless Assistant WGM511 Ver 1.0.0.7 |
| | NETGEAR | WPNT511 | NETGEAR WPNT511 SMART WIZARD Ver1.1.3.0 |

| | | | |
|---|--------------------------|---------------------|--|
| | Linksys | WPC300N | Wireless-N Notebook Adapter Wireless Network Monitor v1.05 |
| | Linksys | WPC54G | Wireless-G Notebook Adapter Wireless Network Monitor Ver 3.1 |
| | Manufacturer Name | Adapter Name | Wireless LAN Utility Name |
| | Linksys | WPC54GX4 | Wireless-G Notebook Adapter with SRX400 Setup Wizard V1.1 |
| | Linksys | WUSB54GP | Wireless-G Portable USB Adapter WLAN Monitor v1.05 |
| | Linksys | WUSB54G | Wireless-G USB Adapter with Wi-Fi Finder |
| | NETGEAR | WG511 v2 | |
| | Linksys | WPC54GX | Wireless-G Notebook Adapter With SRX Wireless Network Monitor v. 1.2 |
| Supported by NSC V2.40 | Linksys | WUSB54GSC | Compact Wireless-G USB Adapter Wireless Network Monitor v1.05 |
| Supported by NSC V2.50 & Quick Wireless Connection V1.00 | Atheros | | Atheros Client Utility |

*1: Because Access Connection service stops, power display of Power Manager becomes invalid.

Software Upgrade History Quick Wireless

| Version | Release date | Remark |
|---------|------------------|---------------|
| V1.00 | August. 12, 2008 | V1.00 release |

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|-----|
| Date: | 09/17/2008 | Originator: | VS |
| PSB #: | PSB.2009.01.003 | Authorization: | Kps |
| Reference: | TI 08-29e Rev. A | Total Pages: | 8 |
| Product(s): | PowerLite 1735W, 735c, 737c, 745c, 755c, 765c, 835p, 1705c, 1715c, 1725, 1815c, 1825, 7850p, 7950p, 8300i with EasyMP.Net optional module, Pro G5150 and Pro G5350 projectors | | |
| Subject: | EMP SlideMaker2 updated Version 1.30 – provides scenario support for WXGA (1280 x 800) resolution | | |

This bulletin was created to inform users about a software update for the EMP SlideMaker2 to Version 1.30.

Description of Change:

Updated software release for creating scenarios in WXGA (16:10) format.

Reason:

- The updated version of EMP SlideMaker2 provides support for creating scenarios in XGA (1024 x 768) resolution and WXGA (1280 x 800) resolution.
- It also provides the ability to select scenarios in XGA (4:3) or WXGA (16:10) format, depending on the projector model used for the presentation.

Limitations:

- When creating a 16:10 scenario, the JPEG image must be in a 16:10 format.
- A 16:10 converted scenario can only be displayed with a WXGA (1280 x 800) projector.
- A 4:3 converted scenario can be displayed with a XGA or WXGA supported projector.
- When adding a PowerPoint slide from a thumbnail window to EMP SlideMaker2 with Microsoft Office 2007, the scenario image file may deteriorate due to an issue with Microsoft Office 2007 SP1.

1) Selecting Aspect Ratio for the Projector being used:

a) Properties Window

The screenshot shows a 'Properties' dialog box with a blue title bar and a close button. It contains several input fields and sections. The 'Output file' section is highlighted with a red dashed border. This section includes the text 'Select projector to be used.' and two radio button options: 'XGA(4:3)' (which is selected) and 'WXGA(16:10)'. Other sections include 'Scenario Name(P):' with an empty text box, 'Scenario Folder(D):' with a text box containing 'C:\Documents and Settings\Epson\M...' and a 'Browse(B)...' button, a 'Configure BGM(W):' checkbox, a play button, and '(M)...', 'Background Color' with a 'Color(C):' dropdown menu showing black, and 'Image Quality' with three radio button options: 'Highest image quality(N):' (About 700KByte/1 Cell), 'High Quality(H):' (About 350KByte/1 Cell, selected), and 'Standard(S):' (About 100KByte/1 Cell). At the bottom are 'OK' and 'Cancel' buttons.

Properties

Scenario Name(P):

Scenario Folder(D): C:\Documents and Settings\Epson\M... Browse(B)...

☐ Configure BGM(W): (M)...

Output file

Select projector to be used.

☒ XGA(4:3) ☐ WXGA(16:10)

Background Color

Color(C):

Image Quality

☐ Highest image quality(N): About 700KByte/1 Cell

☒ High Quality(H): About 350KByte/1 Cell

☐ Standard(S): About 100KByte/1 Cell

OK Cancel

b) Drag and Drop Window

The screenshot shows a 'Note for file conversion' dialog box with a blue title bar and a close button. It contains a message about slideshow replay, a highlighted 'Output file' section, and instructions on how to stop conversion. The 'Output file' section is highlighted with a red dashed border and contains the text 'Select projector to be used.' and two radio button options: 'XGA(4:3)' (selected) and 'WXGA(16:10)'. Below this is a message: 'To stop conversion, right-click the presentation and select [Quit Slideshow] from the context menu.' At the bottom are 'Continue' and 'Stop' buttons.

Note for file conversion

Slideshow will be replayed for PowerPoint file conversion.

Output file

Select projector to be used.

☒ XGA(4:3) ☐ WXGA(16:10)


To stop conversion, right-click the presentation and select [Quit Slideshow] from the context menu.

Continue Stop


2) How to Verify the Aspect Ratio of the Scenario:

The resolution of the scenario is displayed in the window title of the Scenario Window and Scenario Preview as shown below:

a) Scenario Window




b) Scenario Preview




3) Location of download file: EMP SlideMaker2 updated Version 1.30

Download epson12812.exe from the Epson website (www.epson.com)


This is a self extracting file, please follow screen prompts.




After “Clicking” on the “Setup.exe” file, your will be prompted to:



Select you language.



Click "Next" at this screen.



Click "Finish" to complete the installation.

4) **How to User the software:** Please refer to the original documentation that came with your Projector.

5) **Operating Environment:**

| | |
|------------|--|
| OS | Windows 98/98SE/Me/ 2000 Professional/XP Home Edition SP4 / XP SP1,SP2,SP3 Professional(32bit) / Vista non-SP,SP1 Home Basic/Home Premium/Ultimate /Business/Enterprise(32bit) |
| Office | Office2000、 OfficeXP、 Office2003、 Office2007 |
| CPU | At least Celeron 300MHz (Recommended: Celeron 400MHz or above) |
| Memory | At least 64MB (Recommended: 128MB or above) |
| Disk space | At least 50MB |
| Display | At least SVGA (800×600) (Recommended: XGA(1024x768)) |




EPSON PRODUCT SUPPORT BULLETIN

Date: 11/13/2007
PSB #: PSB.2007.11.005A
Reference: TI 07-63e, Rev. A
Product(s): Epson EMP Monitor
Subject: EMP Monitor Version 4.21 Release

Originator: AP
Authorization: Kps
Total Pages: 3

This bulletin was created to inform you of the release of Epson EMP Monitor version 4.21 utility.

New Functions and Improvements:

| New Functions, Improvements | Supported Models | Function / Improvement Description |
|---|---|--|
| Support for 25 languages | All projectors (see Supported Projectors table) | Language support extended to include Chinese (traditional), Dutch, Danish, Polish, Hungarian, Czech, Romanian, Slovene, Norwegian, Swedish, Finnish, Russian, Ukrainian, Greek, Turkish, Arabic. Languages supported in prior version of EMP Monitor: English, Japanese, French, German, Italian, Spanish, Portuguese, Chinese (simplified), Korean |
| Abnormally low air flow notification  | PowerLite 6100i / 6110i | Indicates an abnormal decrease in the force of air flow through the air filter. User should check for air filter obstructions, clean and replace air filter as necessary. This feature is available only for the indicated models. |
| Air flow sensor error  | PowerLite 6100i (with firmware version 1.10 or later) / 6110i | Indicates air flow sensor error. This feature is available only for the indicated models |
| Clean air filter notification  | PowerLite 6110i | User notification to clean air filter. This feature is available only for the indicated model. |

Supported Projectors:

This application supports the following Epson projectors:

| | | |
|-----------------|---|----------------------|
| PowerLite 735c | PowerLite 1715c | PowerLite 1815p |
| PowerLite 737c | PowerLite 6100i | PowerLite 822p |
| PowerLite 745c | PowerLite 7800p | PowerLite 6110i |
| PowerLite 755c | PowerLite 7850p | PowerLite Cinema 500 |
| PowerLite 765c | PowerLite 7900NL | PowerLite 61p |
| PowerLite 830p | PowerLite 8300i / 8300NL | PowerLite 81p |
| PowerLite 835p | PowerLite 8300i with the EasyMP.net Option Module installed | PowerLite 82c |
| PowerLite 1705c | PowerLite 9300NL | PowerLite 821p |

Supported Operating Environment:

| | |
|------------------------------|--|
| Operating System requirement | <ul style="list-style-type: none"> Windows 98SE / Me / NT 4.0 SP6 (except Ukrainian) / 2000 Professional / XP Home Edition / XP Professional (32 bit) / Vista Home Basic / Vista Home Premium / Vista Ultimate (32 bit) / Vista Business (32 bit) / Vista Enterprise (32 bit) (except Arabic) Internet Explorer 5.0 or later |
| Minimum CPU requirement | Pentium MMX 166 MHz (Recommended: Pentium II 233 MHz or faster) |
| Minimum RAM requirement | At least 64 MB (Recommended: 128 MB or more) |
| Drive space requirement | At least 50 MB free |
| Display requirements | SVGA (800 x 600) or higher resolution, 32 bit color display or higher |

Obtaining the Update:

Download epson12456.exe from www.epson.com to get the version 4.21 update for EMP Monitor. This file is a self-extracting archive and will start the installation utility for EMP Monitor.

Software History:

| Version | Release Date | Notes |
|----------------|---------------------|---|
| 3.00 | December 25, 2002 | Added support for the PowerLite 735c |
| 3.01 | February 26, 2003 | Added support for the PowerLite 7800p / 8300i |
| 3.02 | April 18, 2003 | Added support for the PowerLite 7850p / PowerLite 8300i with the EasyMP.net option module installed |
| 3.03 | November 21, 2003 | Added support for the PowerLite Cinema 500 |
| 3.04 | April 1, 2004 | Added support for the Serial ↔ TCP/IP conversion adapter for the PowerLite 61p / 81p |
| 4.01 | October 18, 2004 | Added support for projectors installed on large scale networks |
| 4.02 | August 29, 2005 | Addition of timer function, auto search by specifying IP address. Improvement of communication logs sizes |
| 4.10 | May 8, 2006 | Addition of support for PowerLite 6100i with support for additional monitoring features unique to the PowerLite 6100i |
| 4.20 | May 29, 2007 | Added support for Windows Vista (32 bit) |
| 4.21 | September 26, 2007 | Increased language support to 25 languages |

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|-----|
| Date: | 8/30/2007 | Originator: | DS |
| PSB #: | PSB.2007.08.001 | Authorization: | Kps |
| Reference: | N/A | Total Pages: | 1 |
| Product(s): | Epson Projectors with an HD-15 VGA Analog/Component Input | | |
| Subject: | Elmo HV-110XG Document Camera and Projector Compatibility | | |

This bulletin was created to inform you of an operational issue with the Elmo HV-110XG Document Camera when initially connected to an Epson projector.

Problem:

When attempting to use the Elmo HV-110XG Document Camera connected via the VGA HD15 connection to display content from its document bed. When connected to the projector, the projector displays only the **Blue Screen - No Signal** message and will blink off and on or display just the Blue Screen - No Signal message. When a computer is connected to the Elmo HV-110XG Document Camera and switched to Pass-Through mode, the computer image is displayed correctly by the projector. When switching back to the document table source of the Elmo HV-110XG Document Camera, the problem returns. The Elmo HV-110XG Document Camera puts out a Progressive Scan 20fps signal to the projector's VGA Analog port. This signal is detected at 15 kHz Vertical and 291.8 kHz Horizontal frequencies which are beyond projector sync specifications.

Solution:

With the Elmo HV-110XG Document Camera powered on and connected to the projector via the VGA computer cable, access the **Computer1/Computer2** setting in the projector menu system and select the **Component** setting within the appropriate connection. This will allow the Elmo HV-110XG Document Camera and projector to sync and the projector to display the image of the document camera bed and its contents. However, the image will have a pink cast. To eliminate the pink cast, change the projector setting from Component to **RGB** then to **Auto** and exit from the menu. The projected image will now look normal. This will now allow the Elmo HV-110XG Document Camera to sync and display the image properly to any other connected Epson projector without having to change the projector settings.

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|-----|
| Date: | 04/20/2006 | Originator: | AP |
| PSB #: | PSB.2006.04.002 | Authorization: | Kps |
| Reference: | TI 05-95e Rev. A | Total Pages: | 1 |
| Product(s): | PowerLite 735c / 737c / 745c / 755c / 765c / 835p / 7850p | | |
| Subject: | Animation converter issue found with EMP SlideMaker2 version 1.12 | | |

This bulletin was created to inform users of the EMP SlideMaker2 version 1.12 software of a problem converting certain animations from Microsoft PowerPoint into a Scenario file.

Details:

In the previous EMP SlideMaker2 version 1.11, certain PowerPoint animations were supported in the Scenario files which are created by EMP SlideMaker2. Table 1 shows the list of animations supported in EMP SlideMaker2 version 1.11:

Table 1

| | | | |
|----------|------------|-----------|----------------|
| - Fly | - Blinds | - Box | - Checkerboard |
| - Crawl | - Dissolve | - Peek | - Random Bars |
| - Spiral | - Split | - Stretch | - Strips |
| - Swivel | - Wipe | - Zoom | |

Table 2 shows the list of animations from Table 1 that will not be ported from PowerPoint into the Scenario file by EMP SlideMaker2 version 1.12:

Table 2

| | |
|----------|-----------|
| - Crawl | - Peek |
| - Spiral | - Stretch |
| - Swivel | - Zoom |

Countermeasure:

If it is necessary to use these animations in the Scenario files, use EMP SlideMaker2 version 1.11. Versions of EMP SlideMaker2 subsequent to version 1.12 are expected to incorporate the animations shown in Table 1 above.

EMP SlideMaker2 version 1.11 may be downloaded at www.epson.com. Download epon10855.exe to get this version of the software.

If it is not necessary to use these animations listed in Table 2 above, continue to use the EMP SlideMaker2 version 1.12. Download epon11217.exe at www.epson.com for EMP SlideMaker2 version 1.12.

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|--|-----------------------|-----|
| Date: | 05/11/2005 | Originator: | VS |
| PSB #: | PSB.2005.05.001 | Authorization: | Kps |
| Reference: | TI 03-42e Rev. B, TI 04-45e Rev. D | Total Pages: | 3 |
| Product(s): | PowerLite 735c | | |
| Subject: | Supported Wired and Wireless LAN cards | | |

Reason:

This bulletin is to inform you of the testing results for wired and wireless LAN cards used with the PowerLite 735c.

Models and firmware versions used in the evaluation:

| Projector | PowerLite 735c |
|------------------------|----------------|
| Firmware | V1.11 |
| IM-X firmware (EasyMP) | V1.10 |
| EMP Monitor | Version 3.04 |
| NS Connection | Version 1.32 |

Wireless LAN cards configuration:

- 1) The tested Wireless LAN cards are inserted into the PC and a wireless LAN connection (Ad hoc mode) is made to the projector.
- 2) The tested Wireless LAN cards are inserted into the PC and a wireless LAN connection is made to the projector using an access point (Infrastructure mode).

Items evaluated:

The following items were tested and confirmed to work in both Ad hoc and Infrastructure modes. (WEP is only supported in the Infrastructure mode.)

- 1) All functions of EMP Monitor.
- 2) The following was tested in Infrastructure mode:
 - DHCP, ESSID and WEP can be setup by a browser and function properly.
 - WPA and LEAP work when implemented.
- 3) EMP NS Connection functions properly with the freeze, mute, zoom, and video input change features.
- 4) Power Point slide show works.

Evaluation results for the Wireless LAN cards:

| Wireless LAN card | POWERLITE 735c |
|--|-----------------------|
| 3Com,3crshpw 196, office connect | Pass |
| Cisco Aironet350 AIR-PCM341(2.4GHz) | Pass |
| FMV Notebook (Broadcom BCM4306) | Pass |
| FMV Notebook (Intersil Prism2.5) | Pass |
| Fujitsu FMV-JW181(Agere) | Pass |
| Fujitsu FMV-JW183(Agere HermesII) | Pass |
| Fujitsu FMV-W182(Intersil Prism2.5) | Pass |
| D-Link Airplus XtremeG DWL-G650 | Pass |
| Intel,CR Pro Wireless 2011B, LAN PC Card | Pass |
| Linksys WPC11 Wireless Network PC Card | Pass |
| NetGear 54Mbps wireless PC Card WG511 | Pass |
| SMC 2435W, EZ Connect Turbo, | Pass |
| US Robotic Ref. 9514115MBP | Pass |
| BUFFALO WLI-CB-G54 | Pass |
| ADTEK ADLINK2422C | Pass |
| FMV Notebook (Intel Calexico) | Fail |

Wired LAN cards configuration:

Inserted the wired LAN card to be tested into the projector, connected the projector to a hub and connected two PCs to the same hub.

Items evaluated:

The following items were tested and confirmed to work.

- 1) All functions of EMP Monitor.
- 2) That DHC can be setup using a browser and functions properly.
- 3) EMP NS Connection functions properly with the freeze, mute, zoom, and video input change features.
- 4) Power Point slide show works.
- 5) Using EMP NS Connection, a PC can take control of a projector from another PC.

Evaluation results for the Wired LAN cards:

| Wired LAN Card name | POWERLITE 735c |
|----------------------------|-----------------------|
| 3Com 3C589C-TP | Pass |
| 3Com 3CXE589ET-JP | Pass |
| D-Link DFE670TXD | Pass |
| Fujitsu FMV-J182 | Pass |
| Hawking PN652TX | Pass |
| Linksys PCM100 ver2 | Pass |
| Netgear FA411 | Pass |

| | |
|--|------|
| SMC SMC8041TX | Pass |
| 3Com 10/100 LAN PC Card 3CCFE574BT | Pass |
| PCET100-CL | Pass |
| Linksys 10/100 PC Card | Pass |
| SMC 8041TX V.2, EZ PC Card 10/100, SMC | Pass |
| BUFFALO LPC-PCM-CLX | Pass |
| ELECOM LD-CDK/TX | Pass |
| Corega EtherII PCC-TD | Pass |
| PLANEX FNW-3700-TX | Pass |

The following cards are NOT compatible:

- 01) 3Com 3CCFE575BT-JP
- 02) 3Com 3CXFE575CT-JP
- 03) 3Com 3CXFEM656C
- 04) Megahertz 10/100 LAN CardBus PC Card, 3Com
- 05) Come once (Taiwan card)
- 06) DFE-690TXD- Cardbus 32 bits
- 07) Fujitsu FMV-J184
- 08) Fujitsu FMV-J185
- 09) LPC3-CLTL
- 10) NetGear CardBus Notebook Adapter FA511
- 11) SMC 8036TX, EZ PC Card 10/100, SMC
- 12) TDK LAK-CB100X
- 13) Toshiba LANCB100A
- 14) Xircom CE3B-100BTX
- 15) Xircom CreditCard Ethernet CE3-10/10
- 16) I-O Data PCLA/TE
- 17) PCC-TXD
- 18) Kingston EtherX PC Card KNE-PC2T
- 19) PLANEX GC-1000T
- 20) PLANEX FNW-3800-TX
- 21) BUFFALO LPC-CB-CLGT
- 22) IO DATA ETX-PCM
- 23) ELECOM LD-CBK/TX

NOTE:

No EMI (electro magnetic interference) was done, only a functionality evaluation.

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|-----|
| Date: | 10/08/2004 | Originator: | DS |
| PSB #: | PSB.2004.10.002 | Authorization: | Kps |
| Reference: | TI 04-46e Rev. A | Total Pages: | 14 |
| Product(s): | EMP NS Connection, EMP Network Manager, EMP Monitor, EMP Multi Screen Adjustment, Cinema Color Editor, VCOM Driver | | |
| Subject: | Evaluation results of Epson Projector PC applications tested in Windows XP with SP2. | | |

The purpose of this bulletin is to provide information on Epson PC projector applications tested under the Windows XP SP2 (Service Pack2) environment.

Description:

Information is provided about the evaluation results and recommendations for Epson PC projector applications functionality in Windows XP SP2 Firewall environment.

Reason:

Compatibility testing for functionality of EMP NS Connection, EMP Network Manager, EMP Monitor, EMP Multi Screen Adjustment, Cinema Color Editor, VCOM Driver in the Windows XP SP2 environment.

Results of Windows XP SP2 installation:

Installing SP2 on PCs did not disturb the installation of the above software applications. Also, the application software can be installed on PCs where SP2 or earlier versions are installed without any issues.

The information contained in the following pages provides details for executing the applications in Windows XP SP2.

Executing the Software:

When executing the software noted below for the first time after SP2 installation completes, the following security alert messages are displayed:

[EMP NS Connection]



Security alert screen (EMP NS Connection)

[EMP Network Manager]



Security alert screen (EMP Network Manager)

[EMP Monitor]



Security alert screen (EMP Monitor)

[EMP Multi Screen Adjustment]



Security alert screen (EMP Multi Screen Adjustment)

The Security Alert screen for **EMP Multi Screen Adjustment** is shown after clicking the **Auto** button of **Network** or clicking the **Add** button after entering an IP address in the **IP Address** box.

[Cinema Color Editor]



Security alert screen (Cinema Color Editor)

The functions of the three buttons displayed in the security alert screen are explained below.

- [Keep Blocking]** --- Enables you to register a started application in the “**Exceptions**” program of the Windows Firewall. The network port that the application uses is blocked. By selecting this button once, this security alert message will not be shown when starting the application next time.
- [Unblock]** ----- Enables you to register a started application in the “**Exceptions**” program of the Windows Firewall and unblock the network port that the application uses. By selecting this option once, this security alert message will not be shown when starting the application next time.
- [Ask me later]**----- When you want to select both buttons above or select either one later, this button is selected. The started application is not registered in the “**Exceptions**” program of the Windows Firewall and the network that the application uses is not unblocked. However, when restarting the application, the same security alert message is shown.

- **PC applications will work normally on Windows XP with SP2 if the “Unblock Item” is selected when the security alert screen is shown.**

For the detail operation information of each application, please refer to the following:

Operating Status Report

When selecting the **Keep Blocking** button, the security alert message is closed and the main screen of each application is displayed.


[EMP NS Connection Application]

Port **3620** is necessary for searching for projectors. If this port is blocked, projectors are not detected.

The other applications operate normally. However, there is a case that execution of automatic search disables automatic detection. This occurs when projectors are registered for automatic detection in EMP Monitor before installing SP2, then the registered projectors may not be detected again after SP2 installation. Therefore it is recommended to select **Unblock** in the security alert screen.

If “**Keep Blocking**” has been selected when starting the application for the first time, and the blocking needs to be removed, complete the execution of the application and proceed with unblocking as follows:


- a.) Start the Windows Security Center. Double click the icon in the shape of a shield that is always displayed on the taskbar after the installation of SP2.



Windows Security Center screen


- b.) Select and start **Windows Firewall**

[Caution]
In case the check box for **Don't allow exceptions** is checked (this box is not checked at the initial setting), a network port for software is not unblocked even though the software is checked on **Exceptions**. Make sure this option is not selected.



Windows Firewall screen


c.) Select the **Exceptions** tab and display exceptions program.



•Exceptions screen


d.) Check the check boxes for the software you don't want to block.

[EMP NS Connection] • Check **EasyMP Software** box




Unblock screen (EMP NS Connection)

[EMP Network Manager Application] • Check **EPSON Projector** box




Unblock screen (EMP Network Manager)

[EMP Monitor Application]→ Check **EasyMP.net Software** box




Unblock screen (EMP Monitor)

[EMP Multi Screen Adjustment Application]→ Check **EPSON Projector Software for Multi Screen** box



Unblock screen (EMP Multi Screen Adjustment)

[Cinema Color Editor Application] ---> Check **Cinema Color Editor**.



Unblock screen (Cinema Color Editor)

By following the above procedure, the network port that each application uses is unblocked and they can operate normally.

Corresponding program name to PC applications

| PC Application | Program name |
|-----------------------------|---|
| EMP NS Connection | EasyMP Software |
| EMP Network Manager | EPSON Projector |
| EMP Monitor | EasyMP.net Software |
| EMP Multi Screen Adjustment | EPSON Projector Software for Multi Screen |
| Cinema Color Editor | Cinema Color Editor |

When selecting the **Unblock** button:

The Security Alert screen is closed and the main screen is displayed. Then the search result is displayed.

When selecting the **Ask Me Later** button:

Port **3620** which is used by EMP NS Connection and is necessary for discovering projectors is blocked, and projectors are not detected.

The other applications operate normally. However, there is a case where execution of automatic search disables automatic detection. This occurs when projectors are registered for automatic detection in EMP Monitor before installing SP2, the registered projectors may not be detected after SP2 installation.

VCOM Driver

The following message is shown after the VCOM driver is installed on your PC. Select “No, not this time” item and continue the Plug&Play of the device.



8.) Notes:

When you add the program to Exceptions list, the program can receive network communication from outside. This may cause a security risk such as exposure to a virus attack.

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|--|-----------------------|------------|
| Date: | 04/19/2004 | Originator: | TC |
| PSB #: | PSB.2004.04.005 | Authorization: | <i>Kas</i> |
| Reference: | N/A | Total Pages: | 1 |
| Product(s): | PowerLite 735c/7850p & 8300i (with EasyMP.net module.) | | |
| Subject: | EMP NS Connection failures caused by Remote Control applications | | |

This bulletin was created to inform you of an issue that can occur when using the PowerLite 735c/7850p, 8300i (with EasyMP.net module) and remote control software.

Description of Issue:

The user attempts to run EMP NS Connection on Windows 98SE/Me/2000/XP with the PowerLite 735c/7850p/ 8300i (with EasyMP.net module). When the EMP NS Connection application is launched, it immediately gives an error message stating that EMP NS Connection "FAILED TO INITIALIZE."

Reason:

Epson has found that remote control software, like PCAnywhere and RealVNC, causes a conflict with the EMP NS Connection application. These remote control applications use a "Video Hook Driver" that conflicts with the Epson GDI Monitor driver that is installed and used by EMP NS Connection. Most remote control programs load a small client application at Windows startup and leave an icon in the system tray (located at the bottom right on the desktop) to indicate they have been loaded. In most cases, the remote control software can be turned off by right-clicking on the icon in the system tray and disabling or exiting the program. Remote control applications do not have to be removed from the system in order for EMP NS Connection to run properly; they just need to be turned off. Consult the documentation that came with the remote control software for information on how to disable the software from automatically launching every time the computer is started.

Once the remote control software has been turned off, EMP NS Connection should run without returning an error. If you continue to have issues connecting to the projector, consult the EMP NS Connection Help file or User's Guide for troubleshooting assistance.

Notes:

VNC stands for Virtual Network Computing. It is a remote console utility which allows a user at his computer to assume control of another computer across a network, as if they were sitting in front of that computer.

Remote Control Applications known to conflict with Epson EMP NS Connection

- **PCAnywhere** - versions 32, 9.0, 9.2, 10.0, 10.5 and 11.0 by Symantec
- **Real VNC** - versions 3.3.7 and 4.0 beta by RealVNC with the GNU Library General Public License
- **TightVNC** - version 1.3dev3 based on VNC with the GNU Library General Public License
- **NetworkStreaming** – v. 7.1 (formerly ExpertVNC)

Any other VNC remote control software based on RealVNC under the GNU Library General Public License or remote control programs that load a "Video Hook Driver" (listed in Windows Device Manager under "Display Adapters), can cause similar conflicts.

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|--|-----------------------|-----|
| Date: | 04/02/2004 | Originator: | TC |
| PSB #: | PSB.2004.04.001 | Authorization: | Kps |
| Reference: | N/A | Total Pages: | 2 |
| Product(s): | PowerLite 735c/7850p | | |
| Subject: | Configuring the Projector Name in EasyMP Network Screen Settings | | |

This bulletin was created to provide additional information on how to correctly set the projector name in the EasyMP Network Screen settings window.

Description of issue:

A user is configuring the EasyMP Network Screen settings on a PowerLite 735c or 7850p projector with the remote control in either "Easy Connect Mode" (Ad-Hoc) or "Access Point Mode" (Infrastructure). The user then clicks on the "Advanced" button, selects the "Projector name" field and with the remote control enters a name "Conf Room" (example only) with a space in between the two words. The user clicks OK twice to update the projector but when the EasyMP Network screen reappears, the projector name field still shows the previous name.

Note: The blank space character can be found immediately before the capital letter A as you are toggling through the list of available characters on the remote control.

Reason:

The "Projector name" field does not support a blank space as a valid character. It will allow you to enter it but when you return to the EasyMP Network screen, you will see the Projector name has reverted to the previous name. This occurs in "Easy Connect Mode" (Ad-Hoc) or "Access Point Mode" (Infrastructure). If you need to break the Projector name apart for clarity, use dash "-" or underscore "_" to separate your characters.

Note: You can enter a blank space as a valid character in the ESSID field. The following sections provide a list of valid characters you can use for both of these fields.

"Projector name" valid characters:

Capital letters A-Z, small case a-z, 0-9, and special characters: ! # \$ % & ' () - . @ ^ _ { } ~
No spaces are allowed.

"ESSID" valid characters:

Capital letters A-Z, small case a-z, 0-9, and special characters: ! " # \$ % & ' () * + , - . / : ; < = > ?
@] \ [^ _ ` } | { ~ and blank spaces.

We highly recommend that you limit the number of special characters when entering a name. Use a dash "-" or underscore "_" to separate your characters. Using special characters may cause problems with the naming convention when entering a name in the Projector name or ESSID name fields.


Changing the Projector Name from the Projector EasyMP Menu

Make sure the projector has a unique name so you can identify it when connecting to it from your computer. Follow the steps below to rename the projector:

1. Highlight the Clear button next to the Projector name, and then press Enter on the remote control to clear the text box.
2. Highlight the text box and press Enter (the outline of the text box turns green to indicate you are in Input mode).
3. Tilt the 4-way button (up and down arrows can also be used), up to select individual letters in alphabetical order, or down to select letters in reverse order. Then tilt the button to the right or select the right arrow to move to the next character position.
4. When done typing the new name, press Enter.

Shortcut for entering numbers in the PowerLite 7850p Projector Name or ESSID Fields:

If you want to enter numbers quickly with the PowerLite 7850p, press the Num button on the remote control. The button lights up to indicate that the numeric keypad mode is active. Press the Num button again to exit numeric keypad mode. For more information on setting up your projector please refer to the User's Guide.



EPSON PRODUCT SUPPORT BULLETIN


| | | | |
|--------------------|---|-----------------------|---------------|
| Date: | 02/26/2004 | Originator: | AP |
| PSB #: | PSB.2004.02.009 | Authorization: | AP |
| Reference: | TI03-57e Rev. A | Total Pages: | 1 |
| Product(s): | PowerLite 735c / 7800p / 7850p / 8300i / Cinema 500 | | |
| Subject: | EMP Monitor version 3.03 Update | | |

This bulletin was created to inform you of the availability of EMP Monitor version 3.03. This version of the EMP Monitor software has added support for the PowerLite Cinema 500 projector. All other support for previously supported projectors remains the same.

This software update can be downloaded from the Epson website. Locate and download `epson11017.exe`. This file is a self extracting archive that will automatically start the program installer once the file is extracted to your computer hard drive.

Refer to the documentation provided with your projector for further information about the operation of the EMP Monitor software.

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|---|
| Date: | October 17, 2003 | Originator: | VS |
| PSB #: | PSB.2003.11.001 | Authorization: |  |
| Reference: | TI 03-42e Rev. A | Total Pages: | 3 |
| Product(s): | PowerLite 735c / 7850p / 8300i with EasyMP.net option installed | | |
| Subject: | Supported Wired and Wireless LAN cards | | |

Reason:

This bulletin is to inform you of the testing results for wired and wireless LAN cards used with the PowerLite 735c / 7850p / 8300i with EasyMP.net option installed.

Models and firmware versions used in the evaluation:

| Model | PW firmware version | IM-X•IM-XP firmware version |
|--|---------------------|-----------------------------|
| PowerLite 735c | 1.00 | 1.01 (IM-X) |
| PowerLite 7850p | 2.00 | 1.00 (IM-X) |
| PowerLite 8300i with EasyMP.net option installed | 1.20 | 1.01 (IM-XP) |

Wireless LAN cards configuration:

1. The tested Wireless LAN cards are inserted into the PC and a wireless LAN connection (Ad hoc mode) is made to the projector.
2. The tested Wireless LAN cards are inserted into the PC and a wireless LAN connection is made to the projector using an access point (Infrastructure mode).

Items evaluated:

The following items were tested and confirmed to work in both Ad hoc and infrastructure modes. (WEP is only supported in the infrastructure mode.)

1. All functions of EMP Monitor.
2. DHCP, ESSID and WEP can be setup by a browser and function properly.
3. EMP NS Connection functions properly with the freeze, mute, zoom, and video input change features.
4. Power Point slide show works.

Operating systems used for testing:

Windows 98 and Windows XP

Evaluation results for the Wireless LAN cards:

| Wireless LAN card | PowerLite 735c | PowerLite 7850p | PowerLite 8300i with EasyMP.net |
|--|----------------|-----------------|---------------------------------|
| 3Com,3crshpw 196, office connect | pass | pass | pass |
| Cisco Aironet350 AIR-PCM341(2.4GHz) | pass | pass | pass |
| FMV Notebook (Broadcom BCM4306) | pass | pass | pass |
| FMV Notebook (Intersil Prism2.5) | pass | pass | pass |
| Fujitsu FMV-JW181(Agere) | pass | pass | pass |
| Fujitsu FMV-JW183(Agere HermesII) | pass | pass | pass |
| Fujitsu FMV-W182(Intersil Prism2.5) | pass | pass | pass |
| Fujitsu FMV-JW182(Intersil Prism2.5) | - | pass | pass |
| FMV-STYLISTICTB93(Intersil Prism2.5) | - | pass | pass |
| D-Link Airplus XtremeG DWL-G650 | pass | - | - |
| Intel,CR Pro Wireless 2011B, LAN PC Card | pass | - | - |
| Linksys WPC11 Wireless Network PC Card | pass | - | - |
| NetGear 54Mbps wireless PC Card WG511 | pass | - | - |
| SMC 2435W, EZ Connect Turbo, | pass | - | - |
| US Robotic Ref. 9514115MBP | pass | - | - |
| BUFFALO WLI-CB-G54 | pass | - | - |
| ADTEK ADLINK2422C | pass | Didn't pass | Didn't pass |
| FMV Notebook (Intel Callexico) | Didn't pass | Didn't pass | Didn't pass |

Wired LAN cards configuration:

Insert the wired LAN card to be tested into the projector and make a network connection to the PC.

Items evaluated:

The following items were tested and confirmed to work.

1. All functions of EMP Monitor.
2. DHCP can be setup using a browser and functions properly.
3. EMP NS Connection functions properly with the freeze, mute, zoom, and video input change features.
4. Power Point slide show works.

Evaluation results for the Wired LAN cards:

| Wired Card name | PowerLite 735c | PowerLite 7850p |
|--|----------------|-----------------|
| 3Com 3C589C-TP | pass | pass |
| 3Com 3CXE589ET-JP | pass | pass |
| D-Link DFE670TXD | pass | pass |
| Fujitsu FMV-J182 | pass | pass |
| Hawking PN652TX | pass | pass |
| Linksys PCM100 ver2 | pass | pass |
| Netgear FA411 | pass | pass |
| SMC SMC8041TX | pass | pass |
| 3Com 10/100 LAN PC Card 3CCFE574BT | pass | - |
| PCET100-CL | pass | - |
| Linksys 10/100 PC Card | pass | - |
| SMC 8041TX V.2, EZ PC Card 10/100, SMC | pass | - |
| I-O Data PCLA/TE | Didn't pass | pass |
| PCC-TXD | Didn't pass | Didn't pass |
| Kingston EtherX PC Card KNE-PC2T | Didn't pass | |

The following cards are NOT compatible:

1. 3Com 3CCFE575BT-JP
2. 3Com 3CXFE575CT-JP
3. 3Com 3CXFEM656C
4. Megahertz 10/100 LAN CardBus PC Card (3Com)
5. Come once (Taiwan card)
6. DFE-690TXD- Cardbus 32 bits
7. Fujitsu FMV-J184
8. Fujitsu FMV-J185
9. LPC3-CLTL
10. NetGear CardBus Notebook Adapter FA511
11. SMC 8036TX, EZ PC Card 10/100, SMC
12. TDK LAK-CB100X
13. Toshiba LANCB100A
14. Xircom CE3B-100BTX
15. Xircom CreditCard Ethernet CE3-10/10

NOTE:

No EMI (electro magnetic interference) was done, only a functionality evaluation.

EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|---|-----------------------|-------------------|
| Date: | 08/05/2003 | Originator: | DS |
| PSB #: | PSB.2003.08.001 | Authorization: | 1/4/04 |
| Reference: | N/A | Total Pages: | 4 |
| Product(s): | PowerLite 735c Multimedia Projector | | |
| Subject: | Advanced Menu "Standby Mode" settings and Remote Access | | |

This bulletin was created to inform you of the "Standby Mode" settings, under the Advanced Menu selection for the PowerLite 735c MultiMedia Projector.

Description:

The "Standby Mode" setting information was not included in the User Manual that is bundled with the projector, and is also not included in the User Manual posted on the Epson Website. However, when accessing the menu system on the projector using the remote control, the Advanced Menu does include the "Standby Mode" selection.

When the PowerLite-735c is in standby mode, customers who attempt to attach wirelessly to the projector with either the EMP Monitor Utility, or through their internet browser (Internet Explorer or Netscape) using the TCP/IP address of the projector, cannot detect or attach to it.

Solution:

By default, the **Network Mode** in the Advanced Menu under the Standby Mode section is turned off. In the OFF setting, there is no power to the PC Card slot of the projector. The Network Mode setting needs to be set to **ON** and the projector re-powered for this setting to be activated. After this is done the PC Card slot is then live when the projector is in standby mode, and can be controlled with EMP Monitor or an internet browser.

When an internet browser is being used to access the projector over TCP/IP, a login screen appears requesting a login name and password. By default there is no login name or password set; leave the fields blank and click OK.

Please see the screen shots on the following pages for reference.

Leave the fields blank and click OK.



A Windows-style dialog box titled "Connect to 139.63.2.156". The title bar is blue with a question mark icon and a red close button. Below the title bar is a blue header area with a yellow key icon. The main area has a light beige background. It contains a "User name:" label followed by a text box with a small user icon and a dropdown arrow. Below that is a "Password:" label followed by an empty text box. Under the password box is a checkbox labeled "Remember my password". At the bottom are "OK" and "Cancel" buttons.

Connect to 139.63.2.156


User name:

Password:


☐ Remember my password

OK Cancel

This is the screen that appears after logging in to the projector's Home Page.



Below, note the section called Standby Mode. To the right of Standby Mode is the Network ON/OFF settings.



EPSON PRODUCT SUPPORT BULLETIN

| | | | |
|--------------------|--|-----------------------|-----|
| Date: | 07/16/2003 | Originator: | TC |
| PSB #: | PSB.2003.07.001 | Authorization: | Kps |
| Reference: | N/A | Total Pages: | 1 |
| Product(s): | PowerLite – 735c / 7850p / 8300i (with Easy-MP.Net option installed) | | |
| Subject: | Epson Wireless Projectors and using dual mode 802.11b/g or 802.11b/a wireless PC Cards | | |

This bulletin was created to inform you of issues that have been reported when accessing Epson Wireless Projectors using dual mode 802.11b/g or 802.11b/a wireless PC Cards, either in ad-hoc mode or through dual mode Access Points.

Reason:

The dual mode PC Cards and Access Points tend to have interference and compatibility problems when operating in dual mode.

Solution:

For optimal performance results with Epson 802.11b wireless products, it is recommended that single/native 802.11b mode be used.

If your dual mode wireless PC Card and/or Access Point can be configured to support the 802.11"b" mode only, set it to 802.11"b" only.

Note: In some cases it is not enough to disable dual mode and set the mode to 802.11"b" only; on some dual mode PC cards (802.11b/g or 802.11b/a) the "A" and "G" modes cannot be turned off.